

Large mine landslide harms none in Spain

Sentinel-2 MSI acquired on **07 January 2019** at 11:14:39 UTC
Sentinel-1 CSAR IW acquired on **16 January 2019** at 18:26:06 UTC
Sentinel-2 MSI acquired on **27 January 2019** at 11:13:29 UTC
Sentinel-1 CSAR IW acquired on **28 January 2019** at 18:26:05 UTC

Author(s): Sentinel Vision team, VisioTerra, France - svp@visioterra.fr

Keyword(s): Geohazard, landslide, natural resources, geology, Spain

[2D Layerstack](#)

Fig. 1 - S2 (07.01.2019) - 4,3,2 natural colour - Cobre Las Cruces is a large copper mine in Andalucia, Spain.

[2D view](#)



Fig. 2 - S2 (27.01.2019) - Various colours and layers show as a 1.3 km front in the north-west slope collapsed [300 m lower](#).

[2D animation](#) [2D view](#)



Fig. 3 - S1 (16.01.2019) - vv,vh,vv colour composite - 15 millions cubic meters material spread inside the open pit, more than in Brumadinho. [2D view](#)





Fig. 4 - S1 (28.01.2019) - Production is expected to be halted for 6 months, but luckily no one was injured. [2D animation](#) [2D view](#)



The views expressed herein can in no way be taken to reflect the official opinion of the European Space Agency or the European Union.

More on European Commission space:						
More on ESA:				S-1 website	S-2 website	S-3 website
More on Copernicus program:				SciHub portal	CopHub portal	Inthub portal Colhub portal
More on VisioTerra:				Sentinel Vision Portal	Envisat+ERS portal	Swarm+GOCE portal CryoSat portal Proba-V portal