

Scotland landslide cuts road & transmission lines

Sentinel-2 MSI acquired on **28 October 2018** at 11:43:49 UTC
Sentinel-1 CSAR IW acquired on **02 November 2018** at 18:06:40 UTC
Sentinel-1 CSAR IW acquired on **14 November 2018** at 18:06:40 UTC
Sentinel-2 MSI acquired on **17 November 2018** at 11:43:49 UTC

Author(s): Sentinel Vision team, VisioTerra, France - svp@visioterra.fr

Keyword(s): Geohazard, landslide, infrastructure, energy, lake, archipelago.

[2D Layerstack](#)

Fig. 1 - S1 (02.11.2018) - vv,vh,ndi(vh,vv) colour composite - On the 12.11.2018, a 1km long landslide occurred near the Loch Quoich Dam. [2D view](#)




Fig. 2 - 14.11.2018 - It severed the high voltage transmission lines to Skye and the Western Isles. [2D animation](#) [2D view](#)




Fig. 3 - S2 (28.10.2018) - 8,4,3 colour composite - The landslide closed the road the borders the lake.

[3D view](#) [2D view](#)





Fig. 4 - 17.11.2018 - it also deposited material into the dam spillway, forcing power station operations to be stopped.

[3D animation](#) [3D view](#)



The views expressed herein can in no way be taken to reflect the official opinion of the European Space Agency or the European Union.

More on European Commission space:									
More on ESA:				S-1 website	S-2 website	S-3 website			
More on Copernicus program:				SciHub portal	Cophub portal	Inthub portal	Colhub portal		
More on VisioTerra:				Sentinel Vision Portal	Envisat+ERS portal	Swarm+GOCE portal	CryoSat portal	Proba-V portal	