

MV Nyerere capsizes in Lake Victoria

Sentinel-3 OLCI FR acquired on 16 August 2018 from 07:40:18 to 07:43:18 UTC

Sentinel-2 MSI acquired on 02 September 2018 at 07:55:59 UTC

Sentinel-1 CSAR IW acquired on 12 September 2018 at 03:27:58 UTC

Sentinel-2 MSI acquired on 22 September 2018 at 07:56:19 UTC

Sentinel-1 CSAR IW acquired on 24 September 2018 at 03:27:58 UTC

Author(s): Sentinel Vision team, VisioTerra, France - svp@visioterra.fr

Keyword(s): Emergency, marine traffic, security, accident, Lake Victoria, Tanzania

[2D Layerstack](#)

Fig. 1 - S3 OLCI (16.08.2018) - 10,6,3 colour composite - Ferries shuttle between Ukara & Ukurewe islands, south in Lake Victoria.

[2D view](#)




Fig. 2 - S2 (02.09.2018) - 4,3,2 natural colour - The ship MV Nyerere had a capacity of 100 passengers & 25 tons of cargo.

[2D view](#)




Fig. 3 - S2 (22.09.2018) - The 20.09.2018, it capsized on the trip 50m from its destination, too far for most.

[2D animation](#) [2D view](#)



Fig. 4 - S1 (12 & 24.09.2018) - vv,vh,vv colour composite - At least 265 had boarded which of at least 227 drowned. [2D animation](#) [2D view](#) [2D view](#)



The views expressed herein can in no way be taken to reflect the official opinion of the European Space Agency or the European Union.

More on European Commission space:						
More on ESA:				S-1 website	S-2 website	S-3 website
More on Copernicus program:				SciHub portal	Cophub portal	Inthub portal Colhub portal
More on VisioTerra:				Sentinel Vision Portal	Envisat+ERS portal	Swarm+GOCE portal CryoSat portal Proba-V portal