

Oil spills offshore Republic of Congo

Sentinel-1 CSAR IW acquired on 23 February 2019 at 04:51:36 UTC

Sentinel-1 CSAR IW acquired on 12 April 2019 at 04:51:37 UTC

Sentinel-1 CSAR IW acquired on 12 April 2019 at 04:52:02 UTC

Author(s): Sentinel Vision team, VisioTerra, France - svp@visioterra.fr

Keyword(s): Oil spill, Republic of Congo

[2D Layerstack](#)

Fig. 1 - S1A (12.04.2019) - VV polarisation Radar Cross Section Equalisation (RCSE) - Oil spills from platforms (yellow), Republic of Congo ZEE. [2D view](#)




Fig. 2 - S1A (12.04.2019) - VV polarisation RCSE - Oil spills from platforms (zoom on the cyan polygon of fig.1). [2D view](#)





Fig. 3 - S1A (23.02.2019) - VV polarisation RCSE - Oil spills from platforms (zoom on the cyan polygon of fig.1).

[2D view](#)



Fig.4 - Oil spills coming from platforms detected from Sentinel-1 images acquired during 2019 - Source: VisioTerra.



*The views expressed herein can in no way be taken to reflect the official opinion of the European Space Agency or the European Union.
Contains modified Copernicus Sentinel data 2019, processed by VisioTerra.*

More on European Commission space:



More on ESA:



[S-1 website](#)

[S-2 website](#)

[S-3 website](#)

More on Copernicus program:



[SciHub portal](#)

[CopHub portal](#)

[Inthub portal](#)

[Colhub portal](#)

More on VisioTerra:



[Sentinel Vision Portal](#)

[Envisat+ERS portal](#)

[Swarm+GOCE portal](#)

[CryoSat portal](#)